


# Findings



Water leakage alarm triggered from FCU tray leakage probe

The humidity and room temperature have negative correlation.